

e of the hexagon

Steel: S8.10.12

S - S12

Stain pass

Notes:

S - diameter clamping part

0.42

Table according to ISO 7

	d	c	h	m	dimension
	2.0	6.01		M3	5.5 3.7
	8	5.1	2.75	8.79	M5
	10	6	3.3	11.05	M6
8	4.4	14.38			M8 13
10	5.5	17.77			M10 16
12	6.6	20.03			M12 18
14	7.7	23.35			M14 21
16	8.8	26.75			M16 24
20	11.0	32.95			M20 30
24	13.2	39.55			M24 36